



YM 5021 SPK	12A-377D643
GES 53	12A-378R678
GES 53 H	12A-378Q676
CPG 53 BM	12A-378R641
CPG 53 HM	12A-378S641
530 HM	12A-378S689
HB 53 RLSK	12A-377D690
HB 53 RB	12A-378L690
53 HA	12A-378Q621 12A-379Q621
47B SP	12A-379R611
RB 53-5R	12A-378R628
HB53RT	12A-379N690
53SP	12A-378R622
GES53H	12A-378S676
GES53H	12A-379Q602



27	Honda-Motor
CP503-M, 503HM, GE503H, 12A-378Q676	
27A	Honda-Motor
GE503H, 12A-378Q676 / 53HA, 12A-378Q621	
27B	Honda-Motor
GE503H, 12A-379Q602	
27C	Honda-Motor
53HA, 12A-379Q602	
Hilfsantriebspumpe (High Lift) HB53RT	
28B	RB 53-01, 53SP
29A	
B&S-Motor	
28	GE503, CP503BM, HB53RM, 47B SP
29	RB 53-01, 53SP
YM5021 SPK, HB53RLSK	
30	KAWA-Motor
HB53RT	
31	TEC-Motor
nicht abgebildet, nicht shown	



E3-02540A-01