


LR 55 > 12BI868F637 (2013) > GETRIEBE, MOTOR



NICHT ABGEBILDET / NOT SHOWN  
MOTOR / ENGINE

REF.	FÜR BÄHRER MOD./FOR MOWER MOD.		
26	G 55 (2010) , LR 55 (2010)	BRIGGS & STRATTON	
27	SPB 53 HW (2010), GBR 53 HW		
28	Distanzölöl/ Bushing		
29	LUX 553 HMA, G 55 (2011) LR 55 ( 2011 )		
30	LUX B 53 HMAE (12BJ868Z694) , SPBE 53 HW		
31	HB 53 RLS-HW BE , YM 7021 SPBE HW		
32	MAC 5553 SHW		
33	MF 21 SHWK , MF 21 SHWB		
34	BHR 53 HW ( 12AI868T658 ,Mod.2011 ) 53 SPB-675 HWM ( 12AI868T600 )		
35	SPB HW 53		
36	GBR 53 ECO		
37	BLUE POWER 53 A HW , SPB 53 HW ( 2011,2012,2013 )		
38	BLUE POWER 53 A HW ES , SPBE 53 HW (12AJ869M600)		
39	SPBE 53 HW (12AJ868Z621)		
40	K SPB 53 HW (12AI868T696 ) , 53 SPB-675 HWM ( 12BI868T600 ) , BHR 53 HW (12AI868T658 ,Mod.2012 ) BMR 53 RANCHERO , HW D 6053 TB		
41	LUX B 53 HMAE (12CJ868Z694 )		
42	ERDV21750HW		
50	SPK 53 HW , MBR 18053 HW		Kawa

E3-05341B-01